Job Safety Analysis (JSA)

-TEAM SCREWDRIVERS

STRATODIVER









Development of ROV

Operation	Task	Potential Hazards	Risk Mitigation Method(s)	Responsible
Developing Circuit Board	Soldering	Skin Burn Fume inhalation	 Use soldering iron under expert supervision only Turn off soldering iron when not in use Place soldering iron on its holder after each use to avoid unwanted touch with iron which can cause skin burn Wear respirators while soldering to avoid inhaling fumes Perform soldering in a well-ventilated area only to avoid suffocation Wear protective gloves while using 	Sign
	Waterproofing	Skin Damage Respiratory Irritation	1. Epoxy odor can cause temporary respiratory irritation, to avoid that one must use respirators and work in a well-ventilated area	
Heavy/ Power tools use	 USE HEAVY/POWER TOOLS ONLY UNDER EXPERT SUPERVISION Do no use power tools in explosive atmosphere Three pronged cords must be plugged into a properly grounded installed outlet The wire gauge and the length of the cord must be able to handle the amps of the tool Turn off the tool immediately after use and keep the tool at a safe distance Always wear Electrical Hazards (EH) rated footwear while operating power tools 			

Operation	Task	Potential Hazards	Risk Mitigation Method(s)	Responsible
	Mechanical work	Respiratory Irritation	 Wear respirators to avoid inhaling dust, smoke etc. (airborne particulate matter) Avoid touching freshly cut or 	Sign
		Skin Burn	drilled pieces to prevent skin burn 2. Always wear protective gloves while cutting or drilling pieces	
		Hearing Damage	 Power tools produce sound levels high enough to damage hearing, to prevent hearing loss always wear earplugs or muffs 	
		Saw Injury	 Check condition of the machine/ tool before use. Maintain safe distance from moving blades or drilling bits Turn off machine immediately after use 	
			4. Touch blades or bits only after they have completely stopped	

Required Protective Equipment
Protective Gloves
2. Respirators
3. Earplugs or muffs

Note: Always keep a Medical Kit handy to address any injury

Post Development

Stage	Potential Hazards	Risk Mitigation Method(s)	Responsible
	Heavy Load Strain	While transporting the ROV, do not carry the ROV alone to avoid back strain.	
Transportation	Mishandling	 Handle the ROV with care. Transport the ROV on a transportation cart. 	Sign
	Hand Injury	 Use safety certified hand-holds only Keep your hand at a safe distance from thrust avoid injury 	
Pre-launch/ Assembling the ROV	Eye Damage	Wear safety glasses before operating the ROV and entering the pool.	 Sign
	Slipping	Wear non-slip or closed-toed shoes near the pool to avoid slipping while carrying the ROV	
	Overvoltage	Set appropriate operating voltage	
ROV Demo (Dry Run)	ROV body damage	Keep the ROV on a table/ stand to avoid any physical damage to ROV body.	Sign
	Electrical Connections	Check all the connections, voltage etc. before switching ON the ROV to avoid any electrical damage.	

Stage	Potential Hazards	Risk Mitigation Method(s)	Responsible
	Electrocution	 Before placing the ROV in pool, ensure all the connections are switched off Ensure all the connections are properly wired and dry 	
Launch	Finger Damage	 Use safety certified hand-holds only Keep your fingers at a safe distance from thrusters avoid injury 	 Sign
	Drowning	Wear life jacket before entering the pool	
	Electrocution	In case of leak/ short circuit, immediately switch off the power supply	
Retrieval	Hand Injury	Before retrieving the ROV, ensure that the ROV is off to avoid injury caused by touching thrusters etc.	Sign
Ketrievai	Heavy Load Strain	 Avoid lifting the ROV alone Lift the ROV in a proper body posture to avoid muscle strain due to heavy load 	5.0

Required Training	Required Protective Equipment
Transporting the ROV	 Close-toed shoes while transporting the ROV
2. Assembling the ROV	2. Non- Slip near Pool
3. Setting up wiring and voltage	3. Safety glasses
4. Launching the ROV	4. Protective Gloves
5. Retrieving the ROV	5. Life Jacket

TEAM

SCREWDRIVERS