

Motor system integration diagram (SID)

Two potentiometers are connected to each joystick. Each joystick controls two K166 motor speed controllers. Each K166 motor speed controller operates one motor. Controllers work with nominal 12 volt batteries and power supplies.

