Aqaubot Technicians 2018 Job Safety Analysis

Describe the Job Step	Potential Hazards	Recommended Risk Control Measures	Responsible Person(s)	Initials
Working with Electricity	An employee can be shocked.	 Safety attire is worn. No open wires. No hazardous materials are placed near wires while in use. 	Safety Specialist- Anthony Escatiola	
Using Solder Iron	Employees burning themselves.	 Safety Glasses are worn. Gloves are worn. Area is cleared. 	Safety Specialist- Anthony Escatiola	
Using PVC pipe cutter	Employees cutting themselves.	 Have another employee overseeing the process. Wear protective gloves. Keep hands away from the blade. 	Safety Specialist- Anthony Escatiola	
Using Heat Gun	Employees can be burned by extreme heat.	 Employees should wear gloves. Stay clear of the heated end. 	Safety Specialist- Anthony Escatiola	

Electrical Cords	Employees can trip and fall.	 Can be taped down to minimize tripping. Can be hung above to prevent tripping Be unplugged after each use. 	Safety Specialist- Anthony Escatiola
Technical Documentation	Not being saved.	 Keep flash drive with one designated person. Save a backup to the computer. Stay well communicated with all technical documenters. 	Technical Documenter- Shelby Rivera
Brainstorming Session	Miscommunication	 Make every employee write down ideas and read one at a time aloud. Never discourage an idea/person. Take a vote to ensure fairness. 	CEO-Elijah Euresti Safety Specialist- Anthony Escatiola
Safety Glasses	Not wearing them.	 Wear them. Ensure everyone has a pair assigned to them. They remain in a special place for easy 	Safety Specialist- Anthony Escatiola

		access.	
Meeting Deadlines	Not being met.	 Have calendar posted where all employees are able to view when necessary. Have incentives. (ex. Picking bus seats) Grades based upon meeting cutoff date. CEO-Elijah Euresti Co-CEO- Shelby Rivera 	
Employees Contributing	Work not being evenly distributed.	 Assign specific task along with a deadline for a grade. Do daily checkups. Discuss why work is not being done. Co-CEO-Shelby Rivera 	

EmployeesEmployees have a conflict with one another.Separate them and find the problem.All Aquabot TechniciansTogetheranother.Sit them down to discuss how to fix it.Fix it with necessary steps found while discussing problem.	
--	--